

# SELLER'S PROPERTY DISCLOSURE

Under Maine Law, certain information must be made available to buyers prior to or during preparation of an offer. This statement has been prepared to assist prospective buyers in evaluating this property. This disclosure is not a warranty of the condition of the property and is not part of any contract between the Seller and any buyer. The Seller authorizes the Listing Broker in this transaction to disclose the information in this statement to other real estate licensees and to prospective buyers of this property. The Seller agrees to notify the Listing Broker promptly of any changes in the information and this form will be appropriately changed with an amendment date. Inspections are highly recommended.

**NOTE: DO NOT LEAVE ANY QUESTIONS BLANK. WRITE N/A (NOT APPLICABLE) OR UNKNOWN IF NEEDED.**

PROPERTY LOCATED AT: 488 Gardiner Road Lot #1 Morse Sub., Wiscasset,

## SECTION I. WATER SUPPLY

TYPE OF SYSTEM:  Public  Private  Seasonal  Unknown  
 Drilled  Dug  Other \_\_\_\_\_

MALFUNCTIONS: Are you aware of or have you experienced any malfunctions with the (public/private/other) water system?

Pump:  Yes  No  N/A Quantity: .....  Yes  No  Unknown

Quality:  Yes  No  Unknown

If YES to any question, please explain in the comment section below or with attachment.

WATER TEST: Have you had the water tested? .....  Yes  No

IF YES: Date of most recent test: Unknown Are test results available? .....  Yes  No

To your knowledge, have any test results ever been reported as unsatisfactory or satisfactory with notation?  Yes  No

IF YES, are test results available? .....  Yes  No

What steps were taken to remedy the problem? n/a

• IF PRIVATE:

INSTALLATION: Location: Front - North corner

Installed BY: Larry Oakes DATE of Installation: Approx. 1997

What is the source of your information: Owner/Seller

USE: Number of Persons currently using system? 10

Does system supply water for more than one household? .....  Yes  No  Unknown

COMMENTS: Installed a Water Treatment System

## SECTION II. WASTE WATER DISPOSAL

TYPE OF SYSTEM:  Public  Private  Quasi-Public  Unknown

• IF PUBLIC OR QUASI-PUBLIC:

Have you experienced any problems such as line or other malfunctions? .....  Yes  No

What steps were taken to remedy the problem? Installed new leachfield in 2007

• IF PRIVATE:

TANK:  Septic Tank  Holding Tank  Cesspool  Other: \_\_\_\_\_

Tank Size:  500 Gal.  1000 Gal.  Unknown  Other: \_\_\_\_\_

Tank Type:  Concrete  Metal  Unknown  Other: \_\_\_\_\_

Location: Rear - North Side OR  Unknown Date of Installation: Spring 1997

Date of Last Servicing: Spring 2007 Name of Company Servicing Tank: Pat Jackson

Date Last Pumped: Spring 2007 Have you experienced any malfunctions? .....  Yes  No

If yes, give the date and describe the problem: n/a

LEACH FIELD: .....  Yes  No  Unknown

IF YES: Location: Rear - North Side

Date of installation of leach field: Spring 2007 Installed by: Sam Snow Construction/Pittston

Date of Last Servicing: Never Name of Service Company: n/a

Have you experienced any malfunctions? .....  Yes  No

If yes, give the date and describe the problem & what steps were taken to remedy: n/a

Does Seller have records of the septic system design indicating the number of bedrooms the system was designed for? .....  Yes  No

IF YES, is it available? Yes

SOURCE OF INFORMATION: Owner/Seller

COMMENTS: New Leachfield installed Spring 2007

IS SYSTEM LOCATED IN A SHORELAND ZONE?: .....  Yes  No  Unknown

Is System located in a Coastal Shoreland Zone? .....  Yes  No  Unknown

2010 Page 1 of 3 - SPD Buyer(s) Initials \_\_\_\_\_ Seller(s) Initials L M

**SECTION III. HEATING SYSTEM(S)/SOURCE(S)**

Heating System(s)/Source(s)	SYSTEM 1	SYSTEM 2	SYSTEM 3	SYSTEM 4
TYPE(S)	Oil Fired HWBB	Radiant Heat	Rinnai	
Age of system(s)/source(s)	1997	2006	1995	
Name of company that services system(s)/source(s)	Ron French Peacock Heating	Ron French Peacock Heating	Main Street Fuel	
Date of most recent service call				
Annual consumption per system/source (i.e., gallons, kilowatt hours, cord(s))	600 gals. Not Sleaved	Tenant Pays Sleaved	Tenant Pays Sleaved	
Malfunction per system(s)/source(s) within past 2 years	None	None	None	
Other pertinent information	None	Furnace new 2006	None	

Buried Oil Supply Line:  Yes  No  Unknown Sleeced:  Yes  No  
 Chimney(s) Lined:  Yes  No  Unknown Age: NO Chimney Last Cleaned: n/a  
 Is more than one heat source vented through one flue?  Yes  No  Unknown Had a chimney fire:  Yes  No  Unknown  
 Has chimney been inspected?  Yes  No  Unknown; If Yes, when: n/a

COMMENTS: There is no chimney

**SECTION IV. HAZARDOUS MATERIAL**

The licensee is disclosing that the Seller is making representations contained herein.

A. UNDERGROUND STORAGE TANKS - Current or previously existing:  
 Are there now, or have there ever been, any underground storage tanks on your property?  Yes  No  Unknown  
 IF YES: Are tanks in current use?  Yes  No  
 IF NO above: How long have tank(s) been out of service? n/a  
 What materials are, or were, stored in the tank(s)? n/a  
 Age of tank(s): n/a Size of tank(s): n/a  
 Location: n/a  
 Have you experienced any problems such as leakage? n/a  
 Are tanks registered with the Dept. of Environmental Protection?  Yes  No  Unknown  
 If tanks are no longer in use, have tanks been abandoned according to D.E.P.?  Yes  No  Unknown  
 Comments: None

B. ASBESTOS - Current or previously existing:  
 • as insulation on the heating system pipes or duct work?  Yes  No  Unknown  
 • in the siding?  Yes  No  Unknown • in the roofing shingles?  Yes  No  Unknown  
 • in flooring tiles?  Yes  No  Unknown • other: n/a  Yes  No  Unknown  
 IF YES: Source of Information: Owner/Seller  
 COMMENTS: None

C. RADON/AIR - Current or previously existing:  
 Has the property been tested?  Yes  No  Unknown  
 IF YES: Date: n/a By: n/a  
 Results: n/a If applicable, What remedial steps were taken? n/a  
 Has the property been tested since remedial steps?  Yes  No  Unknown  
 Are test results available?  Yes  No Results & Comments: None

D. RADON/WATER - Current or previously existing:  
 Has the property been tested?  Yes  No  Unknown  
 IF YES: Date: n/a By: n/a  
 Results: n/a If applicable, What remedial steps were taken? n/a  
 Has the property been tested since remedial steps?  Yes  No  Unknown  
 Are test results available?  Yes  No Results & Comments: None

E. LEAD-BASED PAINT/PAINT HAZARDS - Current or previously existing: (Note: Lead-based paint is most commonly found in homes constructed prior to 1978; See EPA Disclosure brochure/form and Maine Lead Warning for more information)  
 Is there now or has there ever been lead-based paint and/or lead-based paint hazards on the property?  Yes  No  Unknown  
 Unknown but possible due to age  
 IF YES, describe location and the basis for the determination: n/a  
 Do you know of any records or reports pertaining to such lead-based paint or lead-based paint hazards:  Yes  No  
 IF YES, describe: \_\_\_\_\_

Are you aware of any cracking, peeling or flaking paint?  Yes  No

COMMENTS: None

2010 Page 2 of 3 - SPD Buyer(s) Initials \_\_\_\_\_ Seller(s) Initials L M

PROPERTY LOCATED AT 488 Gardiner Road Lot #1 Morse Sub., Wiscasset,

F. OTHER HAZARDOUS MATERIALS - Current or previously existing:

TOXIC MATERIAL:  Yes  No  Unknown

OTHER: \_\_\_\_\_

LAND FILL:  Yes  No  Unknown

RADIOACTIVE MATERIAL:  Yes  No  Unknown

Buyers are encouraged to seek information from professionals regarding any specific issue or concern.

**SECTION V. GENERAL INFORMATION**

Is the property subject to or have the benefit of any encroachments, easements, rights-of-way, leases, rights of first refusal, life estates, private way, private road/homeowner associations or restrictive covenants?  Yes  No  Unknown

IF YES: Explain: Restrictive Covenants

What is your source of information: Subdivision Plan

Are there any tax exemption or reduction for this property for any reason including but not limited to: Tree Growth, Open Space and Farmland, Veteran's, Homestead Exemption, Blind, Working Waterfront?  Yes  No  Unknown

IF YES: Explain: n/a

- Leased Equipment (e.g., propane tank, hot water heater, satellite dish): Type: Propane Tanks
- Year Built: See Attached List What year did Seller purchase property? 1992
- Roof: Year Built - Structure: See Attached Year Shingles Installed: See Attached  
Moisture or leakage: None  
Comments: None
- Foundation/Basement: Sump Pump:  Yes  No  Unknown Comments: \_\_\_\_\_  
Moisture or leakage since you owned the property:  Yes  No  Unknown Comments: \_\_\_\_\_  
Knowledge of prior moisture or leakage:  Yes  No  Unknown Comments: \_\_\_\_\_
- Mold: Has the property ever been tested for mold?  Yes  No  Unknown If YES, are test results available?  Yes  No
- Electrical:  Fuses  Circuit Breaker  Other: \_\_\_\_\_  Unknown
- Has the property been surveyed?  Yes  No  Unknown If YES, is the survey available?  Yes  No
- Manufactured Housing: Mobile Home -  Yes  No Modular:  Yes  No
- KNOWN MATERIAL DEFECTS about Physical Condition and/or value of Property, including those that may have an adverse impact on health/safety: None Known

Seller shall be responsible and liable for any failure to provide known information regarding known material defects to the Buyer.

ATTACHMENTS EXPLAINING CURRENT PROBLEMS, PAST REPAIRS OR ADDITIONAL INFORMATION IN ANY SECTION IN DISCLOSURE:  Yes  No

**SECTION VI. ADDITIONAL INFORMATION**

200 Amp Electrical

As Sellers, we have provided the above information and represent that all information is correct. To the best of our knowledge, all systems and equipment, unless otherwise noted on this form, are in operational condition.

Neither Seller nor any Broker makes any representations as to the applicability of, or compliance with, any codes of any sort, whether state, municipal, federal or any other, including but not limited to fire, life safety, building, electrical or plumbing.

Lester Morse  
SELLER  
Lester Morse  
SELLER

December 14, 2010  
DATE  
DATE

I/We have read and received a copy of this disclosure, the arsenic in wood fact sheet, the arsenic in water brochure, and understand that I/we should seek information from qualified professionals if I/we have questions or concerns.

BUYER  
BUYER  
Lester Morse

DATE  
DATE



**PROPERTY DISCLOSURE ADDENDUM  
(Non-Residential Properties)**

TO BE DELIVERED TO BUYERS PRIOR TO OR DURING PREPARATION OF OFFER

REAL ESTATE: RE/MAX Riverside

SELLER: Lester Morse

To the best of Seller's knowledge (check one):

No underground storage facility for the storage of oil or petroleum products exists on the premises.

An underground oil storage facility exists on the premises which is subject to regulation by the Maine Department of Environmental Protection under 38 M.R.S.A. §561, et seq., State of Maine Registration No. \_\_\_\_\_ . The underground facility \_\_\_\_\_ has \_\_\_\_\_ has not been abandoned in place.

Pursuant to Chapter 330 of the Rules of the Maine Real Estate Commission, Licensee discloses that the above-referenced Seller is making no representations regarding current or previously existing known hazardous materials on or in the Real Estate described above, except as follows:

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

(attach additional sheets as necessary)

You are encouraged to seek information from professionals regarding any specific hazardous material issue or concern.

The undersigned hereby acknowledge receipt of this Property Disclosure Addendum prior to the preparation of an offer to purchase the Real Estate.

Date: \_\_\_\_\_

Buyer: \_\_\_\_\_

SELLER: ~~Buyer:~~ Lester Morse  
Lester Morse



Maine Association of REALTORS®/Copyright © 2006.  
All Rights Reserved

RE/MAX Riverside 1 Bowdoin Mill Island Topsham, ME 4086  
Phone: (207)725-8505

Fax: Marie Williams

Produced with ZipForm® by zipLogix 18070 Fifteen Mile Road, Fraser, Michigan 48026 [www.zipLogix.com](http://www.zipLogix.com)



Lester Morse

**Residential Real Property Disclosure Statement**

**MAINE WARNING: LEAD-BASED PAINT HAZARDS**

Any residence built before 1978 may contain lead sufficient to poison children and sometimes adults. LEAD poisoning poses a particular risk if you are pregnant or may become pregnant. LEAD poisoning in young children may produce permanent neurological damage, including learning disabilities, a reduced intelligence quotient (IQ), impaired memory and behavioral problems such as attention deficit hyperactive disorder and a propensity for violence.

Every purchaser of any interest in residential real property on which a residential dwelling was built prior to 1978 is notified that such property may present exposure to lead from lead-based paint that may place young children at risk of developing lead poisoning. The seller of any interest in real property is required to provide the buyer with any information on lead-based paint hazards from risk assessments or inspections in the seller's possession and notify the buyer of any known lead-based paint hazards. A risk assessment or inspection for possible lead-based paint hazards is recommended prior to purchase.

The only way to know with certainty whether lead-based paint hazards are present on the property is to test the property for the presence of lead.

**Acknowledgement of State Disclosure Statement.**

The signature below acknowledges that the seller or potential seller has disclosed to me information about lead-based paint hazards as required by 22 M.R.S.A. Section 1328. This acknowledgement does not constitute a waiver of any rights.

**Seller or potential seller**

Lester Morse 12/14/2010  
Signature Date

Lester Morse  
Name printed

\_\_\_\_\_  
Signature Date

\_\_\_\_\_  
Name printed

**Purchaser or potential purchaser**

\_\_\_\_\_  
Signature Date

\_\_\_\_\_  
Name printed

\_\_\_\_\_  
Signature Date

\_\_\_\_\_  
Name printed

**Acknowledgement of federal disclosure of information  
on Lead-Based Paint and/or Lead-Based Paint Hazards**

**Lead Warning Statement**

*Every purchaser of any interest in residential real property on which a residential dwelling was built prior to 1978 is notified that such property may present exposure to lead from lead-based paint that may place young children at risk of developing lead poisoning. Lead poisoning in young children may produce permanent neurological damage, including learning disabilities, reduced intelligence quotient, behavioral problems, and impaired memory. Lead poisoning also poses a particular risk to pregnant women. The seller of any interest in residential real property is required to provide the buyer with any information on lead-based paint hazards from risk assessments or inspections in the seller's possession and notify the buyer of any known lead-based paint hazards. A risk assessment or inspection for possible lead-based paint hazards is recommended prior to purchase.*

**Seller's Disclosure**

(a) Presence of lead-based paint and/or lead-based paint hazards (check (i) or (ii) below):

(i) \_\_\_\_\_ Known lead-based paint and/or lead-based paint hazards are present in the housing (explain).

---

---

(ii)   x   Seller has no knowledge of lead-based paint and/or lead-based paint hazards in the housing.

(b) Records and reports available to the seller (check (i) or (ii) below):







(i) \_\_\_\_\_ Seller has provided the purchaser with all available records and reports pertaining to lead-based paint and/or lead-based paint hazards in the housing (list documents below).

---

---

(ii)   x   Seller has no reports or records pertaining to lead-based paint and/or lead-based paint hazards in the housing.





Office/Garage/2-residential units

